

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-033 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

October 31, 2006

Donna Winther, Administrator Clark House 1401 N Polk St Moscow, ID 83843

License #: RC-558

Dear Ms. Winther:

On August 10, 2006, a life safety code survey was conducted at Clark House. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire, Life Safety, and Construction Program

EM/slc

c:

Mark Grimes, Supervisor, Facility Fire, Life Safety, and Construction Program



JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T — Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6526 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

August 24, 2006

Donna Winther, Administrator Clark House 1401 N Polk St Moscow, ID 83843 FLECOPY

Dear Ms. Winther:

On August 10, 2006, a life safety code survey was conducted at Clark House. The facility was found to be providing a safe environment and safe, effective care to residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by September 9, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Fire/Life Safety & Sanitation Program

the Buf FOR

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED **IDENTIFICATION NUMBER:** A. BUILDING 01 - ENTIRE BUILDING B. WING 13R558 08/10/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 1401 N POLK ST **CLARK HOUSE MOSCOW, ID 83843** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE (X4) ID ID (EACH DEFICIENCY MUST BE PRECEEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE **PREFIX** PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) R9999 R9999 **Initial Comments** The facility was found to be in substantial compliance with the fire and life safety standards of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on August 10,2006. The surveyor conducting the survey was: Eric Mundell REHS Team Leader Health Facility Surveyor Taylor Barkley Health Facility Surveyor Bureau of Facility Standards TITLE (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

YNOV21 If continuation sheet 1 of 1

STATE FORM



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

Facility Name		Physical Address	Phone Number	
Clark House		1401 N. Polk STreet	えの3・8名) ZIP Code	- 3438
Administrator		City	1	
DOWNA Winther Survey Team Leader		Moscow	83843	
Survey Team Leader	·	Survey Type	Survey Date	
GRIC MUNDELL		FIRE Life Safety	8-10-	06
NON-CORE ISSUES				
ITEM RULE #		DESCRIPTION		DATE RESOLVED
1 404.01	Cordons partial	ly obstructed with functione, plan	ts and	
	Horres.		······································	
	· · · · · · · · · · · · · · · · · · ·			
Response Required Date Signature of Facility Representative				
Hesponse Required Date Signature of Facility Representative				